

State of Utah DEPARTMENT OF NATURAL RESOURCES

gr

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

June 20, 2008

Michael Blakey, Plant Manager Sunnyside Cogeneration Associates P.O. Box 159 Sunnyside, Utah 84539

Subject: Culvert Placement Amendment, Sunnyside Cogeneration Associates, Sunnyside

Refuse/Slurry, C/007/0035, Task ID #2953

Dear Mr. Blakey:

The Division has reviewed your application to change the location of the culvert at the coal storage area. The plan changes were hand drawn on the map (Hydrolic Index Map 7-1). The details of the culvert, as presented, do not conform to the normal process of amendment submittal. The Permittee should supply maps showing permanent detailed features of the culvert and coal storage area. Maps need to be certified by a professional engineer.

The Division has determined that there is a deficiency that must be addressed before the amendment can be determined complete.

R645-301-712, 721, The Permittee has not provided sufficient information in their map to address the minimum requirements of this section. The Permittee needs to make permanent changes to the map and have the map certified by a registered professional engineer.

The plans as submitted are denied. Please resubmit the entire application.

Sincerely,

James D. Smith Permit Supervisor

an

O:\007035.SRS\FINAL\WG2953\2953_Deficiency_ltr.doc

